T-386
Cottingham Farm Orchard Buildings
Goldsborough Neck Road
Easton Vicinity
Ca. 1929-1939
Private

The orchard complex is contained within the historic boundaries of the Cottingham Farm and "New House" properties. The tract is located on 341.80 acres of land to the west of the community of Easton in Talbot County, Maryland. The parcel is located on Goldborough Neck Road and contains four structures. The structures include a picker's shed, a storage building, and two sheds.

The Cottingham Farm Orchard Buildings represents an intact collection of agricultural buildings associated with the historically important development of "canning crops" as a major agricultural product in Talbot County. The property was inherited from Charles Goldsborough estate by his nieces and nephews Robert G. Henry, W. Laird Henry, Charlotte G. Henry, and Mary Y. Fletcher. This site is located on the boundary of two tracts known as "Cottingham Farm" and "New House." The Goldsborough heirs sold the property as part of a larger tract to J. McKinney Willis, Jr. in 1963. The larger tract was subdivided into smaller parcels and sold. The current property owner is unclear. The property was once associated with an orchard which has since vanished.

# Maryland Historical Trust Maryland Inventory of Historic Properties Form

1. Name of Pr	operty				*
historic	Cottingh	nam Farm Orchard Building	IS		7
other	New Ho	use Orchard Buildings			
2. Location	(288	56 Goldsborough	NeckRd Pr	remises Ad	ldress)
street and number	Goldsbo	rough Neck Road		N/A	not for publication
city, town	Easton			_ X	vicinity
county	Talbot				
3. Owner of P	roperty	(give names and mailing	addresses of all owners)		
nameu	nknown				
street and number				telephone	
city, town			state MD	zip code	
4. Location of	Legal D	escription			
Contribut Contribut Determine Determine Recorded Historic S Other:	ing Resource ing Resource ed Eligible for ed Ineligible for by HABS/HA structure Repo	in National Register District in Local Historic District the National Register/Marylan or the National Register/Marylan ER rt or Research Report at MHT	d Register and Register		
6. Classification	on				
district	wnershippublic Xprivateboth	Current Function  X agriculture commerce/trade defense domestic education funerary government health care industry	landscape recreation/culture religion social transportation work in progress unknown vacant/not in use other:		Noncontributing  buildings sites structures objects Total  ntributing Resources ted in the Inventory

7	Docari	ntion
1.	Descri	puon

Inventory No. T-386

#### Condition

_	_ excellent	deteriorated
X	_ good	ruins
	_ fair	altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

#### Summary Description

The orchard complex is contained within the historic boundaries of the Cottingham Farm and "New House" properties. The tract is located on 341.80 acres of land to the west of the community of Easton in Talbot County, Maryland. The parcel is located on Goldborough Neck Road and contains four structures. The structures include a picker's shed, a storage building, and two sheds.

The complex is located directly on Goldborough Neck Road and is arranged in a linear plan along the roadway. The property is surrounded by cultivated agricultural fields. The orchard is no longer extent and no traces remain.

### Picker's Shed, ca. 1935

The main building of the complex is the picker's shed, built ca. 1935. The shed is a two-story timber frame structure with a poured concrete pier foundation. The building is six bays deep with a hayloft on the second level. The side gable roof is clad with corrugated standing-seam metal and has hay hoods on either end.

The principle building entry is located on the south side wall. The wall is clad with vertical wood boards. The original open bays have been enclosed with vertical wood board and steel core doors. There are no windows. A pent roof runs above the open bays.

The west façade is the gable end. The wall is clad with vertical wood boards. The hayloft door is constructed of wood planks with diagonal bracing. There are no windows.

The north façade is clad with vertical wood boards. Three wood plank sliding doors are located on the first level. There are no windows.

The interior of the picker's shed was not accessible at the time of the survey.

#### Storage Building, ca. 1940

The one-and-a-half story storage building is connected to the picker's shed on the east façade. The storage building rests on a brick pier foundation. The building is clad with vertical wood boards. The side gable roof is clad with corrugated standing-seam metal. The interior is accessed via a hinged wood plank door located three-feet above ground level on the south façade. The loading dock has been removed from the south façade, but its outline remains.

The interior of the storage building was not accessible at the time of the survey.

### Sheds (2), ca. 1935 and 1990

The shed, constructed ca. 1935, is a one-story masonry structure. The building rests on a poured concrete slab and is constructed of rusticated, rock-faced concrete masonry units. Plywood sheeting is used to infill the gable ends. The front-gable roof is clad with corrugated standing-seam metal. The building is entered through a hinged wood plank door on the south façade. One rectangular window opening, since boarded up, is located on each remaining façade. A poured concrete slab approximately three-feet by three-feet is located outside the entry door. The interior was not accessible at the time of the survey.

The remaining shed is of modern construction.

Period	Areas of Significance	Check and	l justify below	
1600-1699 1700-1799 1800-1899 1900-1999 2000-	<ul> <li>x agriculture</li> <li>archeology</li> <li>architecture</li> <li>art</li> <li>commerce</li> <li>communications</li> <li>community planning</li> <li>conservation</li> </ul>	economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement	health/medicine industry invention landscape architecture law literature maritime history military	performing arts philosophy politics/government religion science social history transportation other:
Specific dates	1920-1939		Architect/Builder unkn	own
Construction da	tes ca. 1935-1940			
Evaluation for:	9			
0,00	National Register		Maryland Register	Xnot evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

### Summary Statement of Significance

The Cottingham Farm Orchard Buildings represents the area of Agriculture between the years 1935 to 1940. This well preserved example of agricultural buildings is associated with the historically important orchard crops grown in Talbot County. This coincides with the development of "canning crops" as a major agricultural product during the Post-War Recession, the Great Depression, and the New Deal (1920-1939) agricultural period in Talbot County's history. The buildings on the property display the characteristics and building types associated with an orchard operation in Talbot County during this period.

#### Historical Background

The property was inherited from Charles Goldsborough estate by his nieces and nephews Robert G. Henry, W. Laird Henry, Charlotte G. Henry, and Mary Y. Fletcher. This site is located on the boundary of two tracts known as "Cottingham Farm" and "New House." The Goldsborough heirs sold the property as part of a larger tract to J. McKinney Willis, Jr. in 1963. The larger tract was subdivided into smaller parcels and sold. The current property owner is unclear. The property was once associated with an orchard which has since vanished. The property is currently used as a storage and maintenance facility.

# 9. Major Bibliographical References

Inventory No. T-386

Lanier, Gabrielle M. and Bernard L. Herman. Everyday Architecture of the Mid-Atlantic: Looking at Buildings and Landscapes. Baltimore: The Johns Hopkins University Press, 1997.

Levin, Jordan M. "Labor Saving Orchard Equipment Past and Present," Annual Report (Maryland Agricultural Society) 43: 80-83 (1958).

Nobel, Allen G. and Richard K. Cleek. The Old Barn Book. New Brunswick, N.J.: Rutgers University Press, 1997.

Rawson, Richard. Old Barn Plans. New York: Bonanza Books, 1979.

Talbot County Land Records

Whitaker, James H. Agricultural Buildings and Structures. Reston, Va.: Reston Publishing Co., 1979.

## 10. Geographical Data

Acreage of surveyed property
Acreage of historical setting
Quadrangle name

341.80

Easton, MD

Quadrangle scale: 1: 24,000

Verbal boundary description and justification

The boundary of the surveyed property is marked as the boundary as described in the 1967 property deed. The existing parcel portion is concurrent with the historic setting, and includes the remains of the character-defining resources and setting which relate to the property's construction and evolution.

# 11. Form Prepared by


name/title	Amy Barnes, Architectural Historian			
organization	URS Corporation	date	12-08-03	
street & number	7101 Wisconsin Avenue, Suite 700	telephone	301.652.2215	
city or town	Bethesda	state	MD 20814	

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust DHCD/DHCP 100 Community Place Crownsville, MD 21032-2023 410-514-7600



T-386 Cottingham Farm Orchard Buildings Easton, MD USGS Quad (1: 24,000) T-386. 662 50 ВМ, EASTON MUNICIPAL AIRPORT



T- 386 Osthyrham Farm Talbot Co. MD M. Edwards 8/7/03 MD SHIO Shed + Storage bldg. Lok NW ( From Road



T-386 Cotto ham Farm Talbot a. MD M. Edwards 8/1103 MD SHPD Storage blog + shed Look 16



T-386 cotti ham form Talkot a MD M. Edwards 8/7/03 MD SHPD Shear + storage bldg. Look NW3/4 View 315



T-396 Cottychown Farm Talloot Co. MP M. EDWARDS MD SAPO Shed + shorage Blog 3/4 VKIN SC



T-386 Cottingham Farm Talbot Co MD M. Edwards 8/1/03 Storage shed face concrete Looy NW